



East Grimstead Chapel Repaired 1838

The interior of the Chapel at East Grimstead which had become much decayed, and was in a very uncomfortable and unwholesome state from damp, was during the autumn of this year thoroughly repaired

The expence was defrayed by Subscription as stated below.

Although the charge for the repair of the Chancel is not made separately from that of the body of the chapel, it is to be distinctly understood that no portion of the former charge is paid by Parochial Rate, and that all right to the sittings in the Chancel is, as much as ever, reserved to the Rector of the Parish

		£	s	d
James Beauchamp	Carpenter	43	11	1
John Crook	Mason	12	15	0
Smiths Work			6	9
Digging Drain round the Chapel		1	10	0
Total Expence		58	2	10

Source: West Dean St Andrew's Parish Register 1679-1793